

DA08-NA/E, DA10-NA/E

Programming instruction for digital panelmeters with analogue inputs
(09/00)

All Keys on top of the case

Key T1: carries out the adjustment of the selected digit

Key T2: selects the programming digit (is shown by the luminous decimal point).
the final value of display is assigned to the steps 2 and 4 by using of key
after the min. and max. input signal.

Key T3: changes from standard-mode into programming-mode.

MP Display Function

Pr	___0	0 = calibration	external	with external measure signal
		A = calibration	internal currency (-19mA ... +20mA DC)	without external measure signal
		U = calibration	internal voltage (-10V ... +10V DC)	without external measure signal

P0 _ _ _ _ Adjustment of the min. value of display. The value can be positive or negative

P1 P-L Take-over of the min. input signal to be applied.
External calibration: The min. input signal must be connected on the measure input
Internal calibration: Select the min. input value with T1 and T2.
Press the key T3 → the min. value of display adjusted under P 0 will be assigned to the min.
input signal. The display indicates " PL ".

P2 _ _ _ _ Adjustment of the max. value of display. If you need a decimal point you have to place
t on the right position before leaving this code number.

P3 P-H Take-over of the max. input signal to be applied.
External calibration: The max. input signal must be connected on the measure input
Internal calibration: Select the max. input value with T1 and T2.
Press the key T3 → the max. value of display adjusted under P 2 will be assigned to the
max. input signal. The display indicates " P-H ".

P4 _ _ 0 1 Adjustment of the average value of 1 - 99 measurements. The adjusted value will be shown
on the display.
_ L _ _ Line break indicator (- = no, L = yes), only by measuring 4-20 mA. If value falling below
25% of measuring value (< 3 mA) the display indicates -| |- .

P5 _ _ _ 0 Roundness of the last digit. This value effects only the display. Possibilities: 0 → without
roundness, alternative with roundness by steps of 2, 5, or 10.

Option: „F“ (Input function):

P6	___0	Without input function	
	__1__	0 = Function Input off	
		1 = Display dark	4 = displayed ON
		2 = Segmenttest (all segments on)	5 = displayed OFF
		3 = Display hold (Display hold the last value)	6 = displayed HELP

After operating of T3 the display changes back into standard-mode

For a period of about 3 seconds the message " EE " appears. The adjusted values are stored into the
EEPROM during this time.